

BELZONA SAVES A ROOF EXPANSION JOINT

ID: 5338

Industry: *Buildings & Structures*
Application: *RPA-Roof Problem Areas*
Substrate: *Felt paper and tar*
Products: ** Belzona 3111 (Flexible Membrane) ,*

Customer Location: *Troy, MT, USA*
Application Date: *1986*

Problem

The expansion joint on the roof of a bowling alley had split open, caused by movement through temperature variations.



Photograph Descriptions

- * & 2. With the pea gravel removed the problem is obvious ,
- * Problem solved. ,

Application Situation

Roof Expansion Joint

Application Method

The application was carried out in accordance with Belzona System Leaflet RPA-1.

Belzona Facts

The owner was planning to re-tar the entire roof, as recommended by the local roof contractor. Just part of one bucket of reinforced Belzona 3111 solved the problem with the building owner doing the application himself.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve