

A UNIVERSITY KEEPS THE WATER OUT WITH BELZONA

ID: 5348

Industry: Buildings & Structures

Application: RPA-Roof Problem Areas

Substrate: Cement and Brick

Products: * Belzona 3111 (Flexible Membrane) ,
* Belzona 3921 (GSC Surface Conditioner) ,

Customer Location: Washington, USA

Application Date: 1987

Problem

Shortly after the new construction was complete, the expansion joints began leaking into the classrooms below.



Photograph Descriptions

- * Applying Belzona 3921 ,
- * Applying the first coat of Belzona 3111 ,
- * Completed application ,

Application Situation

Expansion joints on new construction.

Application Method

After proper surface preparation, ensuring all contamination was removed, the application was carried out in accordance with Belzona Know-How System Leaflet RPA-1.

Belzona Facts

Belzona 3111 was successfully used to seal the joints, stopping the leaks and keeping the classrooms dry, within a short period of time.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve