

Rig Ballast System Repaired with Belzona

ID: 535

Industry: Oil & Gas

Customer Location: International deep water drilling company - Egypt

Application: VPF-Valves, Pipes and Fittings

Application Date: March 2002

Substrate: Carbon steel

Products: * Belzona® 1121 (Super XL-Metal) ,
* Belzona® 1291 (ES Metal) ,

Problem

Severely corroded and leaking pipes in many sections of the ballast system which threaten the safety of the rig.



Photograph Descriptions

- * General view of the rig ,
- * Leakage of the ballast pipes of the rig ,
- * Repair completed ,
- * Another repair ,

Application Situation

Pipes of the rigs ballast system.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet VPF-11a.

Belzona Facts

The application was carried out while the rig was still in operation saving large sum of money and time in work-stoppage. The repairs protected the rig from serious problems affecting its safety.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve