

# BELZONA PROTECTS STERN TUBE

ID: 5353


Industry: *Marine*  
Application: *SOS-Ships and Offshore Structures*

Customer Location: *Oregon, USA*  
Application Date: *2014*

Substrate: *Steel*  
Products: *\* Belzona 5811 (Immersion Grade),*

## Problem

*The US Army required standard protection against erosion and corrosion when the ship is dry docked.*



## Photograph Descriptions

- \* Stern of the ship ,
- \* Inspecting the grit blast ,
- \* First coat of black Belzona 5811 ,
- \* Second coat of gray Belzona 5811 ,

## Application Situation

Stern tube in a US Army Ship.

## Application Method

The stern tube was grit blasted and then two coats of Belzona 5811 were brushed on. The application was carried out in accordance with Belzona Know-How System Leaflet SOS-2.

## Belzona Facts

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**<sup>®</sup>  
Repair • Protect • Improve

Belzona lasts through the expected time between inspections by the US Army.

---

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

