

# BELZONA STOPS LUBE LEAKS

ID: 5373

Industry: Oil & Gas  
Application: FPA-Floor Problem Areas  
Substrate: Concrete  
Products: \* Belzona 5811 (Immersion Grade) ,  
\* Belzona 9331 (Reinforcing sheet) ,

Customer Location: Beaumont, Texas, USA  
Application Date: April 2014

## Problem

The customer stored lube oil within a small containment area, when leaks would develop they would by-pass and go under the wall onto the ground outside of the containment area.



## Photograph Descriptions

- \* Before repair ,
- \* During repair ,
- \* Application completed ,

## Application Situation

Concrete wall leaking lube oil

## Application Method

Application was carried out in accordance with a modified version of Belzona Know-How System Leaflet FPA-3.

## Belzona Facts

The customer was using vital manpower and resources having to constantly clean-up the ground outside of the containment area,

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

**BELZONA**  
Repair • Protect • Improve

the Belzona application keeps the lube within the containment for easy clean-up.

---

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

