

BELZONA ENCAPSULATES A TRANSFORMER FAUCET

ID: 5381

Industry: Power
Application: VPF-Valves, Pipes and Fittings
Substrate: Brass and steel
Products: * Belzona 1291 (ES-Metal) ,
* Belzona 1161 (Super UW-Metal) ,

Customer Location: Lewiston, ID, USA
Application Date: May 2014

Problem

This leaking faucet was no longer needed, but in order to replace or plug it, the transformer would have to be taken off line and the entire 2000 gallons of oil would need to be drained resulting in lost revenue for this power company.



Photograph Descriptions

- * 1. Prepared surface ,
- * 2. Belzona 1291 applied in the end ,
- * 3. Applying Belzona 1161 ,
- * 4. Application completed ,

Application Situation

Leaking inspection faucet.

Application Method

The faucet was prepared with a grinder, then the active leak was stopped and sealed using Belzona 1291. Belzona 1161 was then used to encapsulate the entire faucet. Application was carried out in accordance with Belzona Know-How System Leaflet VPF-11.

Belzona Facts

This repair used roughly \$30.00 USD of Belzona materials to stop the leak. With a potential 2 week long shut down resulting in unknown possible financial losses, using Belzona's leak solution systems was an easy winning situation saving the company both time and money.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve