

BELZONA REBUILDS PAPER MILL CYCLONE

ID: 5393

Industry: Pulp & Paper
Application: TCC-Tanks and Chemical Containment Areas
Substrate: Carbon steel
Products: * Belzona 1311 (Ceramic R-Metal) ,
* Belzona 1321 (Ceramic S-Metal) ,

Customer Location: Tacoma, WA, USA
Application Date: August 2013

Problem

Erosion had progressed over the years to a point of significant material loss and holes emerging as hog fuel is metered through the cyclone.



Photograph Descriptions

- * Cyclone with lost material piled up around its base ,
- * Welded patches can be seen from outside ,
- * Pack rust and scale in the interior of the cyclone seen from below ,
- * Belzona 1311 applied as fillers and 1st coat of Belzona 1321 is applied ,

Application Situation

Internal lining repair of a cyclone that feeds a hog fuel boiler.

Application Method

As usual, downtime was restricted and we had not been able to see interior surfaces prior to shutdown. Considerable pack rust was encountered, which required needle gunning prior to abrasive blasting. Belzona 1311 & 1321 were hand applied, as confined space offered no room for spray equipment use. Belzona 1311 was used to fill the voids and pits before a coat of Belzona 1321 was applied.

Belzona Facts

The client had an awareness of Belzona's quality materials and confidence to choose repairs over replacement of equipment, which

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

would have been considerably more costly in both time and money.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015	Belzona products are
FS 695214	manufactured under an ISO
ISO 14001:2015	9000 Registered Quality
EMS 695213	Management System.

www.belzona.com

