# BELZONA REPAIRS AND PROTECTS ROOF FROM LEAKS

ID: 5397

Industry: Commercial Facilities

Application: RPA-Roof Problem Areas

Substrate: Rubber

Products: \* Belzona 3111 (Flexible Membrane),

\* Belzona 3921 (GSC Surface Conditioner),

\* Belzona 9311 (Reinforcing Sheet),

#### **Problem**

All five roofs of this commercial business park had numerous water leaks and interior water damage.







Customer Location: KS, USA

Application Date: April 2010



## **Photograph Descriptions**

- \* Overview of the roof,
- \* Areas to be treated,
- \* Belzona 3111 applied to designated areas, including possible penetrations throughout,
- \* Completed applications, including the seams of the entire perimeter,

### **Application Situation**

Property Management Company/Owner was looking for a cost-effective solution to seal several old, leaking roofs for his property in order to buy time for budgeting for a complete overhaul.

## **Application Method**

The rock ballast was moved to expose all joints, seams, penetrations, parapets and patches. These known problem areas then received the fully reinforced Belzona 3111 system remediation. The application was carried out in accordance with Belzona Know-How System Leaflet RPA-1.

#### **Belzona Facts**

Previous patching had proven ineffective and the roofing consultant declared the roof beyond its usable life and called for a complete replacement. Treating just the problem areas alleviated all of the leaks at a substantial savings over tear-off and

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

BELZONA®
Repair : Protect : Improve

replacement.	The tax implications for this "maintenance" procedure proved just as beneficial.
For more example	es of Belzona Know - How In Action, please visit https://khia.belzona.com