

BELZONA WATERPROOFS FLASHINGS SAVING MILLIONS OF DOLLARS OF PRODUCT

ID: 5399

Industry: *Buildings & Structures*

Customer Location: *MO, USA*

Application: *RPA-Roof Problem Areas*

Application Date: *August, 2004*

Substrate: *Galvy/Metal*

Products: ** Belzona 3111 (Flexible Membrane) ,
* Belzona 3921 (GSC Surface Conditioner) ,
* Belzona 9311 (Reinforcement Sheet) ,*

Problem

The material used to seal the flashings on this firewall had become brittle and cracked, creating fissures for water to seep into the building. A solution was needed that was both flexible and UV stable to protect this pharmaceutical storage facility housing millions of dollars of product.



Photograph Descriptions

- * Picture of Warehouse/Storage Structure ,
- * Picture of the damaged flashing in need of repair ,
- * Close-up of Belzona application ,
- * Completed Belzona repair of 80 linear feet of flashing ,

Application Situation

Roof flashings

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet RPA-8 using the fully reinforced Belzona 3111 system.

Belzona Facts

Due to past success with roof repairs for this pharmaceutical facility, Belzona was the confident choice. 850 linear feet of flashing

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

www.belzona.com



was completely sealed and protected in two days. Inspected in 2012, the repair is still perfect.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

