

BELZONA STOPS WATER LEAKING INTO AIRCRAFT HANGAR


ID: 5402

Industry: Buildings & Structures
Application: RPA-Roof Problem Areas
Substrate: Metal and asphalt
Products: * Belzona 3121 (MR7) ,
* Belzona 4111 (Magma-Quartz) ,

Customer Location: MO, USA
Application Date: November, 2004

Problem

This hangar at a municipal airport was leaking water into aircraft hangars due to the damaged flashing and creating a slip hazard near the entry door. Mastics and caulk had failed and a more permanent solution was needed.



Photograph Descriptions

- * 1. Picture of airplane hangar ,
- * 2. Damaged flashing and area of penetration ,
- * 3. Berm built to direct water away from the door ,
- * 4. Picture of completed repair ,

Application Situation

Damaged outer wall flashing of an airplane hangar.

Application Method

The flashing was re-secured to the asphalt with mechanical fasteners. Two coats of Belzona 3121 was then applied a few inches above the flashing and down onto the asphalt. Also, a small berm was fabricated with Belzona 4111 to divert run-off water away from the door.

Belzona Facts

Belzona was chosen as the solution to this problem as it could be accomplished in the harsh winter weather conditions with no disruption to the airport operations. This repair was easily completed in one day with the hangar never being out of service.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve

Copyright © Belzona International Limited 2024