

# BELZONA REPAIRS AND PROTECTS PUMP CASING

ID: 5415

Industry: General Industry  
Application: CEP-Centrifugal Pumps  
Substrate: Cast Iron  
Products: \* Belzona 1111 (Super Metal) ,  
\* Belzona 1341 (Supermetalglide) ,

Customer Location: BC, Canada  
Application Date: July 2002

## Problem

Pump casing was showing signs of degradation. This was from possible contamination during casting process.



## Photograph Descriptions

- \* View of casing showing damaged areas requiring rebuilding. ,
- \* Application of 1st coat of Belzona 1341 in progress ,
- \* Completed application. ,

## Application Situation

Pump Casing

## Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet CEP-3, CEP-5.

## Belzona Facts

A Belzona repair allowed the damaged areas to be quickly rebuilt and the casing protected from further bi-metallic erosion.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

**BELZONA**  
Repair • Protect • Improve