# BELZONA REPAIRS A TANK ROOF AND SAVES THE PLANT FROM SHUTDOWN

ID: 5427

Industry: Chemical & Petrochemical Customer Location: South Louisiana, USA

Application: TCC-Tanks and Chemical Containment Application Date: June 2014

Areas

Substrate: Carbon steel

Products: \* Belzona 1161 (Super UW-Metal),

\* Belzona 9341 (Reinforcement Tape) ,

\* Belzona 4301 (Magma CR Hi-Build),

#### Problem

Vapors were escaping from the tank due to tank top separating. Vapors were also thinning metal in about a 60 sq. ft. area. Customer had welded plates over holes but needed a coating with resistance to sulfuric acid vapors.









## **Photograph Descriptions**

- \* Separation of top from tank,
- \* After coating with Belzona 1161 and Belzona 4301,
- \* Sealing of holes and cracks,
- \* Tank top sealed with Belzona products,

### **Application Situation**

Holes and corrosion on top of sulfuric acid tank and separated top of tank.

#### **Application Method**

The application was carried out in accordance with Belzona Know-How System Leaflets TCC-1 & TCC-5.

#### **Belzona Facts**

Customer was going to have to cut out a 60 sq. ft. of the tank top which would require plant shutdown due to hot work. Estimated savings by using Belzona products and installation was \$80,000.00. this was just the repair cost. Plant shutdown was totally out of conversation. Belzona HAD to work!...and it did!

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

www.belzona.com

BELZONA

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.



www.belzona.com