SHOWER REPAIRED AND PROTECTED WITH BELZONA

ID: 5429

Industry: Marine Customer Location: Dredge Boat, South Louisiana, USA

Application: FPA-Floor Problem Areas Application Date: May 2014

Substrate: Aluminum

Products: * Belzona 1123 (Marine Metal),

* Belzona 1341 (Supermetalglide),

Problem

Crew was using cleaner on shower that was not supposed to be used on aluminum. Cleaner was eroding the metal. Shower floor made of aluminum and drains are brass. Bimetallic corrosion was occurring at drain. So, basically 2 different problems were occurring and destroying the shower floor.









Photograph Descriptions

- * 1. Drain prepared for Belzona application ,
- * 2. Belzona metal filled in areas where corrosion was occuring,
- * 3. Holes had appeared from using the chemical cleaner,
- * 4. Application completed,

Application Situation

Shower stalls on a dredge boat. Boat has 49 showers.

Application Method

Application was carried out in accordance with a modified version of Belzona Know-How System Leaflet FPA-1.

Belzona Facts

Showers are now more aestheticaly pleasing plus corrosion issues have been stopped. The only alternative was to replace the

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

www.belzona.com

BELZONA®

success with Belzona				
For more examples of Belzo	ona Know - How In Action, pl	ease visit https://khia.belz	ona.com	~ 0 0

manufactured under an ISO 9000 Registered Quality FS 695214 ISO 14001:2015 EMS 695213 Management System.

