

# BELZONA REPAIRS A DOCK HOSE BEFORE INSPECTION

ID: 5431


Industry: *Marine*  
Application: *SOS-Ships and Offshore Structures*

Customer Location: *Terminal Dock, Louisiana, USA*  
Application Date: *July 2013*

Substrate: *Rubber*  
Products: *\* Belzona 2311 (SR Elastomer) ,*  
*\* Belzona 2911 (Conditioner) ,*

## Problem

*Over the years as the dock hose had been drug around the deck and over shipside, the hose had been cut and gouged.*



## Photograph Descriptions

- \* 1. Area being prepared for repair. ,
- \* 2. Area after Belzona 2911 applied. ,
- \* 3. Belzona 2311 applied. ,
- \* 4. Finished repair before tape removed. ,

## Application Situation

Rubber Dock Hose with cuts.

## Application Method

After proper surface preparation, the application was carried out in accordance with a modified version of Belzona Know-How System Leaflet SOS-12.

## Belzona Facts

Customer spent less than \$50.00 to repair cosmetic cut in hose for Coast Guard approval to keep using the hose versus spending \$2,500 or more for a new hose.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**<sup>®</sup>  
Repair • Protect • Improve