

# BELZONA REPAIRS A CONVEYOR BELT

ID: 5432

Industry: *General Industry*  
Application: *SHM-Solids Handling Machinery*

Customer Location: *South Louisiana, USA*  
Application Date: *September 2013*

Substrate: *Rubber*  
Products: *\* Belzona 2311 (SR Elastomer) ,*  
*\* Belzona 2911 (Conditioner) ,*

## Problem

*Conveyor belt had a 2" x 2" piece of rubber missing.*



## Photograph Descriptions

- \* 1. The area prepared for repair ,
- \* 2. Application is complete ,

## Application Situation

Conveyor belt with a piece missing.

## Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet SHM-1. The hole in the belt was filled with Belzona 2311.

## Belzona Facts

Customer had made larger repairs with excellent results so it was only natural to repair this hole also. Belzona 2311 enabled the repair to be carried out with minimal downtime.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**<sup>®</sup>  
Repair • Protect • Improve