

BELZONA PROVIDES A NEW SEAMLESS FLOOR AT A SCHOOL

ID: 5438

Industry: Buildings & Structures
Application: FPA-Floor Problem Areas
Substrate: Concrete
Products: * Belzona 5231 (SG Laminate) ,

Customer Location: School, Edmonds, WA, USA
Application Date: 2014

Problem

After twenty years the laminate flooring suffered from age and had become unsanitary. Odor and visible delamination of the laminate was a concern.



Photograph Descriptions

- * 1. Laminate failing in several areas ,
- * 2. Showing signs of use ,
- * 3. Seams suspect to hygiene standards ,
- * 4. Happy customer in a healthy & safe environment ,

Application Situation

School bathroom and classroom floors.

Application Method

After proper surface preparation, the application was carried out in accordance with Belzona Know-How System Leaflets FPA-3 and FPA-8.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve

Belzona Facts

Belzona provided the client with the solution to eliminate safety and health challenges. The adhesion near the seams was failing and delamination increased tears and created holes, so the removal of the contaminated linoleum flooring was of the essence. After adequate preparation of the concrete, Belzona 5231 was applied in two coats, freshening up and creating a safe and healthy area. The application of Belzona 5231 took place after 6pm and was ready for foot traffic by the next morning.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

