

BELZONA REPAIRS AND PROTECTS BULB GENERATOR SET

ID: 5472

Industry: Power
Application: ENC-Engines and Casings
Substrate: Steel and Stainless steel
Products: * Belzona 1111 (Super Metal) ,
* Belzona 1341 (Supermetalglide) ,

Customer Location: Hydropower Plant - France
Application Date: March 2001

Problem

Important infiltration and corrosion between stainless steel jacket and turbine housing.



Photograph Descriptions

- * General view of the housing ,
- * Junction between steel and stainless steel ,
- * Completed repair and protection ,

Application Situation

Bulb generator set.

Application Method

The damaged junction was repaired with Belzona 1111 and protected with Belzona 1341. The application was completed by the customer.

Belzona Facts

Quick, on-site and cold repair.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve