

BELZONA PROTECTS BUFFER STONE WITH INTERNAL COATING

ID: 5474

Industry: Oil & Gas
Application: TCC-Tanks and Chemical Containment Areas
Substrate: Steel
Products: * Belzona 1591 (Ceramic XHT),

Customer Location: Refinery, France
Application Date: October 2013

Problem

The pressurized equipment was subject to abrasion and regularly cleaned with high pressure. The temperature of the hydrocarbons was up to 150°C.



Photograph Descriptions

- * Application on grit-blasted substrate ,
- * Completing the application on the top part of the tank ,
- * Inspecting the thickness of the coating ,

Application Situation

Buffer store with a diameter of 3m and length of 11m, transporting crude oil.

Application Method

The application was carried out during a shutdown of the refinery. The entire application was completed in a one coat system.

Belzona Facts

The application was completed in only 2 days. Belzona 1591 was specified by the inspection service of the refinery.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve