

# BELZONA FLOATING ORANGE HOSE

ID: 55

Industry: Oil & Gas

Customer Location: Offshore Oil Port in the Gulf of Mexico, USA

Application: SOS-Ships and Offshore Structures

Application Date: Ongoing since 1994

Substrate: Rubber

Products: \* Belzona® 2211 (MP Hi-Build Elastomer) ,  
\* Belzona® 9341 (Reinforcement Tape) ,

## Problem

Massive, deep cut in the hose.



## Photograph Descriptions

- \* Repair procedure in progress using Belzona® 9341 (Reinforcement Tape) and special layering technique. ,
- \* Belzona® 2211 (MP Hi-Build Elastomer) almost cured. ,
- \* Floating hose ready to go. ,

## Application Situation

Floating rail hose

## Application Method

The application was carried out in accordance with Belzona Know-How Leaflet SOS-12.

## Belzona Facts

Replacement of the 45-foot long hose would have cost approximately \$40,000 with long delivery time. The Belzona application cost only \$1,000 saving the customer nearly \$40,000.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

**BELZONA**  
Repair • Protect • Improve