

BELZONA FORMS 24" FLAT FACE FLANGE

ID: 5517

Industry: Oil & Gas
Application: VPF-Valves, Pipes and Fittings
Substrate: Carbon steel
Products: * Belzona 1111 (Super Metal) ,

Customer Location: Oil Major, North Sea, UK
Application Date: November 2014

Problem

Existing coating had failed leading to corrosion of the vessel internals and severe loss of metal on the adjacent flanges. This 24 inch flange was for the Perspex sight port.



Photograph Descriptions

* 1. The damaged flange face. Note damage to internal lining 2. Aluminium former in place 3. Former removed showing reformed flange face with Belzona 1111 4. flange re-assembled with Perspex window in place ,

Application Situation

Deck water seal of inert gas generator system on an FPSO. Seal handles sea water at ambient temperatures.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet VPF-13. An aluminium former was fabricated. This was accurately positioned using shims to allow accurate reconstruction of the flange face with Belzona 1111 to be completed.

Belzona Facts

Client was unable to use hot work and had restricted time. Application was carried out over a weekend and the entire solution, from first notification, including former fabrication, was completed in less than a week. A number of other flanges were reformed using the Belzona re-usable formers. The vessel was returned to service with minimum disruption to the production cycle.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve