

BELZONA UPGRADES SAFETY OF STAIRS AT MULTI-STORY CAR PARK

ID: 5558

Industry:

Application: FPA-Floor Problem Areas

Substrate: Concrete


Products: * Belzona 4411 (Granogrip) ,
* Belzona 9221 (Surefoot Aggregate White) ,

Customer Location: Local Council, UK

Application Date: April 2008

Problem

Steps presented a slip hazard to users of the car park.



Photograph Descriptions

- * Original painted grip system ,
- * Belzona 4411 grip system applied in 2008 ,
- * Application revisited in 2015 ,

Application Situation

Worn steps.

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-8. Belzona 9221 was encapsulated in Belzona 4411 and applied in an even coat.

Belzona Facts

These stairs have been used by thousands of people over the last 7 years and they were shutting down these stairs every couple of

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve

months to re-paint prior to the Belzona 4411 application.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

