

# BELZONA UPGRADES SAFETY OF STAIRS AT MULTI-STORY CAR PARK

ID: 5558

## Industry:

Application: FPA-Floor Problem Areas

Substrate: Concrete


Products: \* Belzona 4411 (Granogrip) ,  
\* Belzona 9221 (Surefoot Aggregate White) ,

Customer Location: Local Council, UK

Application Date: April 2008

## Problem

Steps presented a slip hazard to users of the car park.



## Photograph Descriptions

- \* Original painted grip system ,
- \* Belzona 4411 grip system applied in 2008 ,
- \* Application revisited in 2015 ,

## Application Situation

Worn steps.

## Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-8. Belzona 9221 was encapsulated in Belzona 4411 and applied in an even coat.

## Belzona Facts

These stairs have been used by thousands of people over the last 7 years and they were shutting down these stairs every couple of

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**<sup>®</sup>  
Repair • Protect • Improve

months to re-paint prior to the Belzona 4411 application.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015	Belzona products are
FS 695214	manufactured under an ISO
ISO 14001:2015	9000 Registered Quality
EMS 695213	Management System.

[www.belzona.com](http://www.belzona.com)

