

BELZONA KEEPS WATER OUT AND THE ENVIRONMENT SAFE

ID: 5586

Industry: Oil & Gas
Application: SOS-Ships and Offshore Structures

Customer Location: FPSO, Brazil
Application Date: April 2015

Substrate: Rubber
Products: * Belzona 2911 (Elastomer QD Conditioner),
* Belzona 2211 (MP Hi-Build Elastomer),
* Belzona 9341 (Reinforcement Tape),

Problem

The crew noticed a tear in the rubber of the off loading hose and took the quick decision to call in the experts to repair it with Belzona.



Photograph Descriptions

- * Damaged area ,
- * Belzona 2911 ,
- * Reinforcement sheet ,
- * Completed application ,

Application Situation

Off loading hose damage.

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet SOS-12. The surface was roughened before the application of Belzona 2911, followed by the reinforced system of Belzona 2211 to the damaged areas.

Belzona Facts

The quick decision to make the repair with Belzona prevented the seawater to continue into the inside of the hose, which could lead to the disruption of the hose and oil leak. The repair was made in just four hours.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com



For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

