

BELZONA REPAIRS PVC PUMP

ID: 559

Industry: General Industry
Application: CEP-Centrifugal Pumps
Substrate: PVC
Products: * Belzona® 1111 (Super Metal) ,

Customer Location: Construction company - Egypt
Application Date: September 2003

Problem

Cracked casing



Photograph Descriptions

- * The crack in the PVC pump ,
- * Stabilising the crack ,
- * Cracks after preparation ,
- * Cracks repaired ,

Application Situation

PVC dosing pumps (2)

Application Method

Application was carried out in accordance with a modified version of Belzona Know-How System leaflet CEP-6. The cracks were stabilized by drilling and widening it then filled with Belzona® 1111.

Belzona Facts

PVC cracks are critical problems, welding cannot be used here. Belzona stops the cracks in a short time saving the high costs of new units.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve