

BELZONA REPAIRS RUBBER PRESS ROLL

ID: 5636

Industry: *Pulp & Paper*

Customer Location: *Northeastern USA*

Application: *SHM-Solids Handling Machinery*

Application Date: *June 2015*

Substrate: *Rubber & steel*

Products: ** Belzona 2311 (SR Elastomer) ,
* Belzona 2911 (Elastomer QD Conditioner) ,*

Problem

Rubber press roll had a hole caused by a tool impact, which made the roll unusable and not being able to create a smooth gasket.



Photograph Descriptions

- * Rubber press roll ,
- * Deep hole in press roll ,
- * Cleaned, prepped and masked off hole to be repaired ,
- * Repaired hole and used a razor blade to cut and smooth final surface ,

Application Situation

Rubber press roll used to laminate gasket sheets together.

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet SHM-9. The surface preparation and the application was carried out with the use of hand tools.

Belzona Facts

The cost of the Belzona materials used for the application was less than \$100. Replacement of the roll would have cost the asset owners thousands of dollars.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

www.belzona.com

