

BELZONA TANK BASE SEALING SYSTEM OFFERS COST-EFFECTIVE SOLUTION

ID: 5650

Industry: Chemical & Petrochemical
Application: GSS-Gaskets, Seals and Shims
Substrate: Carbon steel and concrete
Products: * Belzona 3211 (Lagseal) ,

Customer Location: International Petroleum Company, China
Application Date: October 2014

Problem

The original tank base seal cracked allowing moisture penetration to tank base. This led to corrosion under the tank base.



Photograph Descriptions

- * Overview of the tank farm ,
- * Damaged tank base ,
- * Applying Belzona 3211 ,
- * Completed application ,

Application Situation

Storage tank at tank farm.

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet GSS-3.

Belzona Facts

The Belzona system met the clients' urgent requirement for a system to resist water, weather and fire. The cost effective Belzona system has been specified into the client's global standard and all the 40 tanks at the farm are to be protected in 2 years.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

Copyright © Belzona International Limited 2024