

of material. This is the second pump this fire department has repaired and coated. These pumps pump 1000 gpm. Prior to coating the pump ran at 1750 rpm to pump 1000 gpm. After coating, the pump only runs at 1600 rpm to pump 1000 gpm.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

