

BELZONA SMOOTHS AIRPORT RUNWAY


ID: 5685

Industry: General Industry
Application: FPA-Floor Problem Areas
Substrate: Concrete
Products: * Belzona 4111 (Magma-Quartz),

Customer Location: Airport, Northern Texas, USA
Application Date: 2014

Problem

Prior patching material failed. A steel plate was used to cover the hole.



Photograph Descriptions

- * Old patch failed and removed ,
- * Hole prepared for application ,
- * Bulk material to fill the hole ,
- * Finished with pure Belzona 4111 ,

Application Situation

Airport runway

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet FPA. Old and loose material was removed. Then, a mixture of gravel and Belzona 4111 was used to bulk up the patch. A batch of pure Belzona 4111 was used to finish the job.

Belzona Facts

The material was applied at 11:00 PM and the runway was open by 8:00 AM.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

