

# BELZONA SMOOTHS AIRPORT RUNWAY


ID: 5685

Industry: General Industry  
Application: FPA-Floor Problem Areas  
Substrate: Concrete  
Products: \* Belzona 4111 (Magma-Quartz) ,

Customer Location: Airport, Northern Texas, USA  
Application Date: 2014

## Problem

Prior patching material failed. A steel plate was used to cover the hole.



## Photograph Descriptions

- \* Old patch failed and removed ,
- \* Hole prepared for application ,
- \* Bulk material to fill the hole ,
- \* Finished with pure Belzona 4111 ,

## Application Situation

Airport runway

## Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet FPA. Old and loose material was removed. Then, a mixture of gravel and Belzona 4111 was used to bulk up the patch. A batch of pure Belzona 4111 was used to finish the job.

## Belzona Facts

The material was applied at 11:00 PM and the runway was open by 8:00 AM.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015	Belzona products are
FS 695214	manufactured under an ISO
ISO 14001:2015	9000 Registered Quality
EMS 695213	Management System.

[www.belzona.com](http://www.belzona.com)

