

BELZONA TAKES THE SLIP OUT OF THE FLOOR

ID: 5686

Industry: Buildings & Structures

Customer Location: Building and Structures, Northern Texas, USA

Application: FPA-Floor Problem Areas



Application Date: 2014

Substrate: Concrete

Products: * Belzona 4131 (Magma-Screed) ,
* Belzona 5811 (Immersion Grade) ,

Problem

The VCT square tiles were coming up with the water dripping on them from the ice machine, causing a sanitary and slipping problem.



Photograph Descriptions

- * Tile removed ,
- * Floor levelled with Belzona 4131 ,
- * Coated floor prepared for nonskid ,
- * Completed floor application ,

Application Situation

Tile was coming loose and holding water, causing mold and a slip problem in hotel.

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet FPA. The tile was removed and the floor was levelled with Belzona 4131. A coat of Belzona 5811 was applied over the whole area and a coat with aggregate was applied in front of the ice machine.

Belzona Facts

The floor was recently fixed and lasted only a few months. Belzona provided a permanent solution for the customer.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve