

BELZONA BEARING HOUSING REPAIR

ID: 571

Industry: *General Industry*

Customer Location: *Iron and steel manufacturing factory, Egypt*

Application: *MPT-Mechanical Power Transmission*

Application Date: *December 2003*

Substrate: *Cast Iron*

Products: ** Belzona® 1111 (Super Metal) ,*

Problem

Oversized bearing housing due to bearing failure.



Photograph Descriptions

- * General view of the bearing housing ,
- * Rebuilding of bearing housing using forming technique ,
- * Bearing housing after repair ,
- * The upper part of bearing housing repaired ,

Application Situation

Exhauster fan bearing housing

Application Method

Application was carried out in accordance with Bezona Know-How System Leaflet MPT-7.

Belzona Facts

Belzona repaired the worn out bearing housing without welding or machining, preventing the heat distortion of coventional welding repairs. A special adjusting part has been fabricated to ensure accurate dimensions.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve