

# BELZONA GIVES NEW LIFE TO GROCERY STORE FLOOR

ID: 5772

Industry: Buildings & Structures

Application: FPA-Floor Problem Areas

Substrate: Concrete



Products: \* Belzona 4111 (Magma-Quartz) ,  
\* Belzona 4911 (Magma TX Conditioner) ,

Customer Location: Grocery Store, Northern Texas, USA

Application Date: 2014

## Problem

Receiving floor at a grocery store was so rough that groceries were falling off the pallets.



## Photograph Descriptions

- \* Preparation completed and conditioned with Belzona 4911 ,
- \* Mixing station ,
- \* Application in progress ,
- \* Completed application ,

## Application Situation

Damaged floor

## Application Method

The floor was ground and conditioned with Belzona 4911 to prepare the surface for application. Then, 1/4 of Belzona 4111 was applied to level the floor.

## Belzona Facts

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve

The application was started in the evening and ready for service by the first delivery. A previous product had failed within months.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015	Belzona products are
FS 695214	manufactured under an ISO
ISO 14001:2015	9000 Registered Quality
EMS 695213	Management System.

[www.belzona.com](http://www.belzona.com)

