

SPALLED STEPS NO LONGER A SAFETY HAZARD WITH BELZONA REPAIR


ID: 5814

Industry: Buildings & Structures
Application: FPA-Floor Problem Areas
Substrate: Concrete
Products: * Belzona 4131 (Magma-Screed) ,
* Belzona 4911 (Magma TX Conditioner) ,

Customer Location: Waterloo, ON, Canada
Application Date: September 2014

Problem

The stairs had spalled due to environmental freeze and thaw effect.



Photograph Descriptions

- * Prior to application ,
- * Completed application ,
- * Completed application ,

Application Situation

Stairs to a memorial recreation center.

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-10 for fixing or securing anchor bolts or hand rails. The surface was prepared using a grinder and the surface was brushed to remove any loose concrete. Belzona 4911 was applied to the area using a stiff bristle brush. Belzona 4131 was applied directly onto the conditioned surface in accordance with Belzona Instructions For Use.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve

Belzona Facts

Belzona 4131 has outstanding environmental protection, is impermeable to water and provides long term protection. Belzona 4131 is easily applied using a trowel, thus, no specialist tools are required.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

