

CONVENIENT BELZONA CONVEYOR BELT REPAIR

ID: 583

Industry: Power

Application: SHM-Solids Handling Machinery

Customer Location: Power Industry, Bulgaria


Application Date: October 2003

Substrate: Rubber

Products: * Belzona® 2311 (SR Elastomer),
* Belzona® 2911 (QD Conditioner),

Problem

Joint failing due to moisture.



Photograph Descriptions

- * Original joint ,
- * Repair area masked off and conditioned ,
- * Completed application ,

Application Situation

Previously vulcanized joints in coal conveyor utilizing Tip Top.

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet SHM-6.

Belzona Facts

The Belzona repair minimizes down-time and is accomplished without specialist vulcanizing equipment. this application lasted in excess of three years and Belzona is routinely used at the facility for belt repairs.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve