

# BELZONA SEALS VALLEY GUTTERS

ID: 5887

Industry: *General Industry*  
Application: *RPA-Roof Problem Areas*  
Substrate: *Cast iron*  
Products: *\* Belzona 3131 (WG Membrane),*

Customer Location: *Manufacturing Plant, Scotland*  
Application Date: *October 2014*

## Problem

*Full replacements of the gutter would have caused excessive disruption to the working areas below.*



## Photograph Descriptions

- \* Length of gutters before surface preparation ,
- \* Section of gutter showing build up of dirt & corrosion ,
- \* Length of gutter coated ,
- \* Standing water still an issue but the gutter is now leak free ,

## Application Situation

Several valley gutters constructed from cast steel had begun to leak from the joints. These leaks were causing damage to the stored materials below.

## Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet RPA-6.

## Belzona Facts

Belzona 3131, a liquid applied membrane, allowed the applicators to coat the existing substrate without removing large sections of

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

**BELZONA**  
Repair • Protect • Improve

the roof. The Belzona 3131 system is flexible, which has allowed a long lasting repair over the problem joints where competitor materials had failed.

---

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

