

TIRE REPAIR WITH BELZONA ELASTOMER

ID: 589

Industry: General Industry

Application: SHM-Solids Handling Machinery

Customer Location: Processing plant, Bulgaria

Application Date: December 2003

Substrate: Rubber

Products: * Belzona® 2211 (MP Hi-Build Elastomer) ,

Problem

A piece of metal penetrated the sidewall.



Photograph Descriptions

- * Size of the tire clearly evident ,
- * The metal alongside and the damage it caused ,
- * Prepared and conditioned area ,
- * Finished Elastomer repair ,

Application Situation

Rear tire of front end loader.

Application Method

Application was carried out in accordance with a modified version of Belzona Know-How System Leaflet SHM-1.

Belzona Facts

The client insisted on repairing this tire based on his good experience with Belzona solutions and the alternative expensive replacement. The tire was in service nearly one year following the repair.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA®**
Repair • Protect • Improve