

SHAFT JOURNAL OF STONE CRUSHER REPAIRED WITH BELZONA

ID: 590

Industry: Chemical & Petrochemical
Application: MPT-Mechanical Power Transmission

Customer Location: Chemical industry, Bulgaria
Application Date: July 2002

Substrate: Steel
Products: * Belzona® 1321 (Ceramic S-Metal) ,
* Belzona® 9411 (Release Agent) ,

Problem

Shaft damaged by seized bearing.



Photograph Descriptions

- * Preparing shaft surface ,
- * Forming with manufactured pipe clamp ,
- * View of repair with former removed ,

Application Situation

Main shaft of primary stone crusher

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet MPT-2.

Belzona Facts

Belzona allowed vital equipment to be returned to service with minimum disruption to production.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve