

SHAFT JOURNAL OF STONE CRUSHER REPAIRED WITH BELZONA

ID: 590

Industry: *Chemical & Petrochemical*
Application: *MPT-Mechanical Power Transmission*

Customer Location: *Chemical industry, Bulgaria*
Application Date: *July 2002*

Substrate: *Steel*
Products: ** Belzona® 1321 (Ceramic S-Metal) ,*
** Belzona® 9411 (Release Agent) ,*

Problem

Shaft damaged by seized bearing.



Photograph Descriptions

- * Preparing shaft surface ,
- * Forming with manufactured pipe clamp ,
- * View of repair with former removed ,

Application Situation

Main shaft of primary stone crusher

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet MPT-2.

Belzona Facts

Belzona allowed vital equipment to be returned to service with minimum disruption to production.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve