

CONCRETE STEP REPAIR WITH BELZONA

ID: 5912

Industry: *Buildings & Structures*

Customer Location: *Building & Structures, North Carolina, USA*

Application: *FPA-Floor Problem Areas*

Application Date: *August 2015*

Substrate: *Concrete*

Products: ** Belzona 4411 (Granogrip),
* Belzona 4111 (Magma-Quartz),*

Problem

Concrete steps were broken and deteriorating.



Photograph Descriptions

- * Prior to application ,
- * Preparing the surface by removing busted concrete ,
- * Application of Belzona 4411 with some aggregate ,
- * Completed application ,

Application Situation

Concrete steps leading up to the entrance of building.

Application Method

The old concrete was removed so that Belzona 4111 could fill in the spots. After the steps were smoothed over, Belzona 4411 was added with some aggregate.

Belzona Facts

This entranceway was an eyesore and a trip hazard. The use of Belzona products provided a solution to both issues in a cost effective manner. This area is used frequently for special events, such as private catering and weddings.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve