

BEARING HOUSING REPAIR WITH BELZONA

ID: 593

Industry: Water / Wastewater
Application: MPT-Mechanical Power Transmission

Customer Location: Watersupply company, Bulgaria
Application Date: April, 2003

Substrate: Cast iron
Products: * Belzona® 1111 (Super Metal) ,

Problem

Housing damage after bearing seized leading to increased clearance.



Photograph Descriptions

- * Preparing surface ,
- * Belzona® 1111 applied ,
- * Housing with restored dimensions after machining ,

Application Situation

Centrifugal pump bearing housing

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet MPT-6.

Belzona Facts

Belzona solution saved both time and replacement cost allowing the equipment to be quickly returned to operation.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

Copyright © Belzona International Limited 2025