# BELZONA "SMOOTH RIDE" APPLICATION OF EXPANSION JOINTS SAVES BOTTLES

ID: 5998

Industry: Buildings & Structures Customer Location: Montana, USA

Application: FPA-Floor Problem Areas Application Date: 2003

Substrate: Concrete

Products: \* Belzona 4911 (Magma TX Conditioner),

\* Belzona 4111 (Magma-Quartz),

\* .

#### **Problem**

The warehouse floor suffered from uneven surfaces and bumps, causing product spills and long man hours to ensure cleanliness and safety.









### **Photograph Descriptions**

- \* Concrete below grade at old doorway.,
- \* Applying Belzona 4911 after surface preparation. ,
- \* Belzona 4111 trowelled smoothly over the defect areas.,
- \* Repair holding up to forklift traffic years later.,

# **Application Situation**

Concrete floor at a warehouse.

# **Application Method**

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-1.

#### **Belzona Facts**

The relationship between the suppliers, customers and the warehouse started to go down the hill due to frequent delays in shipping out the products. Interruptions in loading due to the need to clean up spillage and breakage caused delays in the shipping of

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

www.belzona.com

product. This simple repair from a complete kit of Belzona 4111 went very easily and all the products needed were in the kit. This repair made for smooth travel on the forklifts and stopped the product waste, saving both money and good customer relations.	
For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com SO 9001:2015 Belzona products are	0.0

manufactured under an ISO 9000 Registered Quality FS 695214 ISO 14001:2015 EMS 695213 Management System.

www.belzona.com

