

BELZONA "SMOOTH RIDE" APPLICATION OF EXPANSION JOINTS SAVES BOTTLES

ID: 5998

Industry: *Buildings & Structures*

Customer Location: *Montana, USA*

Application: *FPA-Floor Problem Areas*

Application Date: *2003*

Substrate: *Concrete*

Products: ** Belzona 4911 (Magma TX Conditioner) ,*

** Belzona 4111 (Magma-Quartz) ,*

** ,*

Problem

The warehouse floor suffered from uneven surfaces and bumps, causing product spills and long man hours to ensure cleanliness and safety.



Photograph Descriptions

- * Concrete below grade at old doorway. ,
- * Applying Belzona 4911 after surface preparation. ,
- * Belzona 4111 trowelled smoothly over the defect areas. ,
- * Repair holding up to forklift traffic years later. ,

Application Situation

Concrete floor at a warehouse.

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-1.

Belzona Facts

The relationship between the suppliers, customers and the warehouse started to go down the hill due to frequent delays in shipping out the products. Interruptions in loading due to the need to clean up spillage and breakage caused delays in the shipping of

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

www.belzona.com

EMS 695213

Management System.



product. This simple repair from a complete kit of Belzona 4111 went very easily and all the products needed were in the kit. This repair made for smooth travel on the forklifts and stopped the product waste, saving both money and good customer relations.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

