

BELZONA REPAIRS NATURAL GAS VALVE

ID: 602

Industry: Oil & Gas
Application: VPF-Valves, Pipes and Fittings
Substrate: Cast iron
Products: * Belzona® 1111 (Super Metal) ,

Customer Location: Oil and gas production company, Egypt
Application Date: February 2003

Problem

Gas leaks had been worsened by traditional weld repairs.



Photograph Descriptions

- * General view of the valve ,
- * Traditional welding failed causing more leakage ,
- * Surface preparation ,
- * Application completed ,

Application Situation

Natural gas valve

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet VPF-1.

Belzona Facts

Belzona successfully solved this serious problem with a simple and fast technique, avoiding heat distortion to the surface and at a low cost.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve