

BELZONA COLD REPAIR TO LEAKING PIPE JOINT

ID: 6067

Industry:

Application: VPF-Valves, Pipes and Fittings

Substrate: Steel pipe, Copper Pipe & brass fittings

Products: * Belzona 1212 ,

Customer Location: City Council, Newcastle, UK

Application Date: March 2016

Problem

On investigation it was found that pipe was leaking at the joint and fittings were corroded.



Photograph Descriptions

- * Pipe/Joint location ,
- * Close up of corroded joint ,
- * Joint sealed/repaired ,

Application Situation

Tenant on 10th floor of block of Flats was experiencing a leak from flat above causing water damage.

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet VPF-11 application method a).

Belzona Facts

Due to the location and access of the leak, hot work could not be carried out. The Belzona cold applied application was the ideal and cost effective solution. Belzona has excellent adhesion to the different metals involved.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve