SWIMMING POOL FILTERS SEALED WITH BELZONA

ID: 6139

Industry: General Industry Customer Location: Engineering Co, Slovenia

Application: TCC-Tanks and Chemical Containment Application Date: May 2016

Areas

Substrate: Stainless steel
Products: * Belzona 1212,

* Belzona 5811DW2 (DW Immersion Grade),

Problem

Filters were leaking due to defective welds









Photograph Descriptions

- * One of the filter drums,
- * Belzona 1212 application to welds,
- * Belzona 5811DW2 application,
- * Completed application ,

Application Situation

Swimming pool filler drums.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflets TCC-1 and TCC-4. Belzona 1212 was used to seal and smooth welds before applying Belzona 5811DW2 to provide overall corrosion protection.

Belzona Facts

Time to get back in service was of most importance. The Belzona system provided fast and long term repair and protection to old filter drums.

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

www.belzona.com

