

# BELZONA SEALS NEW PIPES IN HOTEL WATER RESERVOIR

ID: 6168

Industry: *Buildings & Structures*  
Application: *FPA-Floor Problem Areas*  
Substrate: *Carbon Steel , Concrete*  
Products: *\* Belzona 4111 (Magma Quartz) ,*

Customer Location: *Hotel, Israel*  
Application Date: *2013*

## Problem

*New pipes drilled into water reservoir needed to be anchored and sealed to the tank wall.*



## Photograph Descriptions

- \* 1 & 2. Internal application to secure new pipes ,
- \* 3 & 4 External fixing of pipes ,

## Application Situation

Hotel water reservoir needed new piping.

## Application Method

Application carried out in accordance with Belzona Know How System Leaflets FPA-5

## Belzona Facts

The customer was looking for reliable solution since on previous experience leaks had occurred around the pipes. Belzona 4111 provides high bond strength without shrinking enabling a secure leak free installation.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**<sup>®</sup>  
Repair • Protect • Improve