

BELZONA SEALS NEW PIPES IN HOTEL WATER RESERVOIR

ID: 6168

Industry: *Buildings & Structures*
Application: *FPA-Floor Problem Areas*
Substrate: *Carbon Steel , Concrete*
Products: ** Belzona 4111 (Magma Quartz) ,*

Customer Location: *Hotel, Israel*
Application Date: *2013*

Problem

New pipes drilled into water reservoir needed to be anchored and sealed to the tank wall.



Photograph Descriptions

- * 1 & 2. Internal application to secure new pipes ,
- * 3 & 4 External fixing of pipes ,

Application Situation

Hotel water reservoir needed new piping.

Application Method

Application carried out in accordance with Belzona Know How System Leaflets FPA-5

Belzona Facts

The customer was looking for reliable solution since on previous experience leaks had occurred around the pipes. Belzona 4111 provides high bond strength without shrinking enabling a secure leak free installation.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve