

BELZONA ELIMINATES TRIP HAZARD FROM DRAIN COVERS

ID: 6185

Industry: Buildings & Structures
Application: FPA-Floor Problem Areas
Substrate: Concrete
Products: * Belzona 4111 (Magma Quartz) ,
* Belzona 4411 (Granogrip) ,

Customer Location: Shopping centre, Bankstown, Australia
Application Date: May 2004

Problem

Existing drain covers were proud of surface creating a potential trip hazard.



Photograph Descriptions

- * 1. The raised drain plate ,
- * ,
- * 2. Belzona 4111 to rebuild drain ,
- * ,
- * 3. The plate fixed in place ,
- * ,
- * 4. Coated with Belzona 4411 ,

Application Situation

Drain covers in various areas of shopping centre.

Application Method

Application was carried out in accordance with Belzona Know- How System leaflets FPA-1 & FPA-8. Concrete was ground away and Belzona 4111 used to re-install plates at ground level. Plates were then coated with Belzona 4411 Granogrip to provide slip resistance.

Belzona Facts

The finished outcome eliminated the trip hazard and installation did not impact on normal operations around the shopping centre.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve