

# BELZONA ELIMINATES TRIP HAZARD FROM DRAIN COVERS

ID: 6185

Industry: Buildings & Structures  
Application: FPA-Floor Problem Areas  
Substrate: Concrete  
Products: \* Belzona 4111 (Magma Quartz),  
\* Belzona 4411 (Granogrip),

Customer Location: Shopping centre, Bankstown, Australia  
Application Date: May 2004

## Problem

Existing drain covers were proud of surface creating a potential trip hazard.



## Photograph Descriptions

- \* 1. The raised drain plate ,
- \* ,
- \* 2. Belzona 4111 to rebuild drain ,
- \* ,
- \* 3. The plate fixed in place ,
- \* ,
- \* 4. Coated with Belzona 4411 ,

## Application Situation

Drain covers in various areas of shopping centre.

## Application Method

Application was carried out in accordance with Belzona Know- How System leaflets FPA-1 & FPA-8. Concrete was ground away and Belzona 4111 used to re-install plates at ground level. Plates were then coated with Belzona 4411 Granogrip to provide slip resistance.

## Belzona Facts

The finished outcome eliminated the trip hazard and installation did not impact on normal operations around the shopping centre.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**<sup>®</sup>  
Repair • Protect • Improve