

BELZONA REPAIRS CONCRETE AFTER BOLLARD REMOVAL

ID: 6190

Industry: Buildings & Structures
Application: FPA-Floor Problem Areas
Substrate: Concrete
Products: * Belzona 4111 (Magma Quartz),

Customer Location: Shopping Centre, Bankstown, Australia
Application Date: September 2004

Problem

Removal of bollards left rough concrete substrate that was a trip hazard.



Photograph Descriptions

- * 1. Damaged concrete ,
- * ,
- * 2. Conditioner applied ,
- * ,
- * 3. Mixing Belzona 4111 ,
- * ,
- * 4. Applying Belzona 4111 ,

Application Situation

Damaged concrete in 48 areas where bollards were removed

Application Method

Application was carried out in accordance with Belzona Know How System Leaflet FPA-1.

Belzona Facts

Ability to feather edge the Belzona 4111 enabled damaged areas to be quickly and simply levelled to eliminate trip hazard.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve